

| Класс прочности | Режим работы | | | | | | | | | | Класс прочности |
|-----------------|----------------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|-----------------|
| M | | | | | 1Bm | 1Am | 2m | 3m | 4m | 6m | M |
| P | | | | 1Bm | 1Am | 2m | 3m | 4m | 5m | - | P |
| S | | | 1Bm | 1Am | 2m | 3m | 4m | 5m | - | - | S |
| T | | 1Bm | 1Am | 2m | 3m | 4m | - | - | - | - | T |
| V | | 1Am | 2m | 3m | 4m | - | - | - | - | - | V |
| Номер крюка | Грузоподъемность, кг | | | | | | | | | | Номер крюка |
| 006 | 320 | 250 | 200 | 160 | 125 | 100 | - | - | - | - | 006 |
| 010 | 500 | 400 | 320 | 250 | 200 | 160 | 125 | 100 | - | - | 010 |
| 012 | 630 | 500 | 400 | 320 | 250 | 200 | 160 | 125 | 100 | - | 012 |
| 020 | 1000 | 800 | 630 | 500 | 400 | 320 | 250 | 200 | 160 | 125 | 020 |
| 025 | 1250 | 1000 | 800 | 630 | 500 | 400 | 320 | 250 | 200 | 160 | 025 |
| 04 | 2000 | 1600 | 1250 | 1000 | 800 | 630 | 500 | 400 | 320 | 250 | 04 |
| 05 | 2500 | 2000 | 1600 | 1250 | 1000 | 800 | 630 | 500 | 400 | 320 | 05 |
| 08 | 4000 | 3200 | 2500 | 2000 | 1600 | 1250 | 1000 | 800 | 630 | 500 | 08 |
| 1 | 5000 | 4000 | 3200 | 2500 | 2000 | 1600 | 1250 | 1000 | 800 | 630 | 1 |
| 1.6 | 8000 | 6300 | 5000 | 4000 | 3200 | 2500 | 2000 | 1600 | 1250 | 1000 | 1.6 |
| 2.5 | 12500 | 10000 | 8000 | 6300 | 5000 | 4000 | 3200 | 2500 | 2000 | 1600 | 2.5 |
| 4 | 20000 | 16000 | 12500 | 10000 | 8000 | 6300 | 5000 | 4000 | 3200 | 2500 | 4 |
| 5 | 25000 | 20000 | 16000 | 12500 | 10000 | 8000 | 6300 | 5000 | 4000 | 3200 | 5 |
| 6 | 32000 | 25000 | 20000 | 16000 | 12500 | 10000 | 8000 | 6300 | 5000 | 4000 | 6 |
| 8 | 40000 | 32000 | 25000 | 20000 | 16000 | 12500 | 10000 | 8000 | 6300 | 5000 | 8 |
| 10 | 50000 | 40000 | 32000 | 25000 | 20000 | 16000 | 12500 | 10000 | 8000 | 6300 | 10 |
| 12 | 63000 | 50000 | 40000 | 32000 | 25000 | 20000 | 16000 | 12500 | 10000 | 8000 | 12 |
| 16 | 80000 | 63000 | 50000 | 40000 | 32000 | 25000 | 20000 | 16000 | 12500 | 10000 | 16 |
| 20 | 100000 | 80000 | 63000 | 50000 | 40000 | 32000 | 25000 | 20000 | 16000 | 12500 | 20 |
| 25 | 125000 | 100000 | 80000 | 63000 | 50000 | 40000 | 32000 | 25000 | 20000 | 16000 | 25 |
| 32 | 160000 | 125000 | 100000 | 80000 | 63000 | 50000 | 40000 | 32000 | 25000 | 20000 | 32 |
| 40 | 200000 | 160000 | 125000 | 100000 | 80000 | 63000 | 50000 | 40000 | 32000 | 25000 | 40 |
| 50 | 250000 | 200000 | 160000 | 125000 | 100000 | 80000 | 63000 | 50000 | 40000 | 32000 | 50 |
| 63 | 320000 | 250000 | 200000 | 160000 | 125000 | 100000 | 80000 | 63000 | 50000 | 40000 | 63 |
| 80 | 400000 | 320000 | 250000 | 200000 | 160000 | 125000 | 100000 | 80000 | 63000 | 50000 | 80 |
| 100 | 500000 | 400000 | 320000 | 250000 | 200000 | 160000 | 125000 | 100000 | 80000 | 63000 | 100 |
| 125 | - | 500000 | 400000 | 320000 | 250000 | 200000 | 160000 | 125000 | 100000 | 80000 | 125 |
| 160 | - | - | 500000 | 400000 | 320000 | 250000 | 200000 | 160000 | 125000 | 100000 | 160 |
| 200 | - | - | - | 500000 | 400000 | 320000 | 250000 | 200000 | 160000 | 125000 | 200 |
| 250 | - | - | - | - | 500000 | 400000 | 320000 | 250000 | 200000 | 160000 | 250 |